



**Model M216B**

**Force ring, 80k lb comp., 18 pC/lb, charge output**

**Installation and Operating Manual**

**For assistance with the operation of this product,  
contact PCB Piezotronics, Inc.**

**Toll-free: 800-828-8840  
24-hour SensorLine: 716-684-0001  
Fax: 716-684-0987  
E-mail: [info@pcb.com](mailto:info@pcb.com)  
Web: [www.pcb.com](http://www.pcb.com)**



## Repair and Maintenance

PCB guarantees Total Customer Satisfaction through its “Lifetime Warranty Plus” on all Platinum Stock Products sold by PCB and through its limited warranties on all other PCB Stock, Standard and Special products. Due to the sophisticated nature of our sensors and associated instrumentation, **field servicing and repair is not recommended and, if attempted, will void the factory warranty.**

Beyond routine calibration and battery replacements where applicable, our products require no user maintenance. Clean electrical connectors, housings, and mounting surfaces with solutions and techniques that will not harm the material of construction. Observe caution when using liquids near devices that are not hermetically sealed. Such devices should only be wiped with a dampened cloth—never saturated or submerged.

In the event that equipment becomes damaged or ceases to operate, our Application Engineers are here to support your troubleshooting efforts 24 hours a day, 7 days a week. Call or email with model and serial number as well as a brief description of the problem.

## Calibration

Routine calibration of sensors and associated instrumentation is necessary to maintain measurement accuracy. We recommend calibrating on an annual basis, after exposure to any extreme environmental influence, or prior to any critical test.

PCB Piezotronics is an ISO-9001 certified company whose calibration services are accredited by A2LA to ISO/IEC 17025, with full traceability to SI through N.I.S.T. In addition to our standard calibration services, we also offer specialized tests, including: sensitivity at elevated or cryogenic temperatures, phase response, extended high or low frequency response, extended range, leak testing, hydrostatic pressure testing, and others. For more information, contact your local PCB Piezotronics distributor, sales representative, or factory customer service representative.

## Returning Equipment

If factory repair is required, our representatives will provide you with a Return Material Authorization (RMA) number, which we use to reference any information you have already provided and expedite the repair process. This number should be clearly marked on the outside of all returned package(s) and on any packing list(s) accompanying the shipment.

## Contact Information

PCB Piezotronics, Inc.  
3425 Walden Ave.  
Depew, NY14043 USA  
Toll-free: (800) 828-8840  
24-hour SensorLine: (716) 684-0001  
General inquiries: [info@pcb.com](mailto:info@pcb.com)  
Repair inquiries: [rma@pcb.com](mailto:rma@pcb.com)

For a complete list of distributors, global offices and sales representatives, visit our website, [www.pcb.com](http://www.pcb.com).

## Safety Considerations

This product is intended for use by qualified personnel who recognize shock hazards and are familiar with the precautions required to avoid injury. While our equipment is designed with user safety in mind, the protection provided by the equipment may be impaired if equipment is used in a manner not specified by this manual.

Discontinue use and contact our 24-Hour Sensorline if:

- Assistance is needed to safely operate equipment
- Damage is visible or suspected
- Equipment fails or malfunctions

For complete equipment ratings, refer to the enclosed specification sheet for your product.

## Definition of Terms and Symbols

The following symbols may be used in this manual:



### **DANGER**

Indicates an immediate hazardous situation, which, if not avoided, may result in death or serious injury.

**CAUTION**

Refers to hazards that could damage the instrument.

**NOTE**

Indicates tips, recommendations and important information. The notes simplify processes and contain additional information on particular operating steps.

**The following symbols may be found on the equipment described in this manual:**



This symbol on the unit indicates that high voltage may be present. Use standard safety precautions to avoid personal contact with this voltage.



This symbol on the unit indicates that the user should refer to the operating instructions located in the manual.



This symbol indicates safety, earth ground.



PCB工业监视和测量设备 - 中国RoHS2公布表

PCB Industrial Monitoring and Measuring Equipment - China RoHS 2 Disclosure Table

| 部件名称                                             | 有害物质   |        |        |              |            |              |
|--------------------------------------------------|--------|--------|--------|--------------|------------|--------------|
|                                                  | 铅 (Pb) | 汞 (Hg) | 镉 (Cd) | 六价铬 (Cr(VI)) | 多溴联苯 (PBB) | 多溴二苯醚 (PBDE) |
| 住房                                               | O      | O      | O      | O            | O          | O            |
| PCB板                                             | X      | O      | O      | O            | O          | O            |
| 电气连接器                                            | O      | O      | O      | O            | O          | O            |
| 压电晶体                                             | X      | O      | O      | O            | O          | O            |
| 环氧                                               | O      | O      | O      | O            | O          | O            |
| 铁氟龙                                              | O      | O      | O      | O            | O          | O            |
| 电子                                               | O      | O      | O      | O            | O          | O            |
| 厚膜基板                                             | O      | O      | X      | O            | O          | O            |
| 电线                                               | O      | O      | O      | O            | O          | O            |
| 电缆                                               | X      | O      | O      | O            | O          | O            |
| 塑料                                               | O      | O      | O      | O            | O          | O            |
| 焊接                                               | X      | O      | O      | O            | O          | O            |
| 铜合金/黄铜                                           | X      | O      | O      | O            | O          | O            |
| 本表格依据 SJ/T 11364 的规定编制。                          |        |        |        |              |            |              |
| O：表示该有害物质在该部件所有均质材料中的含量均在 GB/T 26572 规定的限量要求以下。  |        |        |        |              |            |              |
| X：表示该有害物质至少在该部件的某一均质材料中的含量超出 GB/T 26572 规定的限量要求。 |        |        |        |              |            |              |
| 铅是欧洲RoHS指令2011/65/ EU附件三和附件四目前由于允许的豁免。           |        |        |        |              |            |              |

CHINA RoHS COMPLIANCE

| Component Name                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      | Hazardous Substances |              |              |                                |                                |                                       |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|--------------|--------------|--------------------------------|--------------------------------|---------------------------------------|
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     | Lead (Pb)            | Mercury (Hg) | Cadmium (Cd) | Chromium VI Compounds (Cr(VI)) | Polybrominated Biphenyls (PBB) | Polybrominated Diphenyl Ethers (PBDE) |
| Housing                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             | O                    | O            | O            | O                              | O                              | O                                     |
| PCB Board                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           | X                    | O            | O            | O                              | O                              | O                                     |
| Electrical Connectors                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               | O                    | O            | O            | O                              | O                              | O                                     |
| Piezoelectric Crystals                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              | X                    | O            | O            | O                              | O                              | O                                     |
| Epoxy                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               | O                    | O            | O            | O                              | O                              | O                                     |
| Teflon                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              | O                    | O            | O            | O                              | O                              | O                                     |
| Electronics                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         | O                    | O            | O            | O                              | O                              | O                                     |
| Thick Film Substrate                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                | O                    | O            | X            | O                              | O                              | O                                     |
| Wires                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               | O                    | O            | O            | O                              | O                              | O                                     |
| Cables                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              | X                    | O            | O            | O                              | O                              | O                                     |
| Plastic                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             | O                    | O            | O            | O                              | O                              | O                                     |
| Solder                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              | X                    | O            | O            | O                              | O                              | O                                     |
| Copper Alloy/Brass                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  | X                    | O            | O            | O                              | O                              | O                                     |
| <p>This table is prepared in accordance with the provisions of SJ/T 11364.</p> <p>O: Indicates that said hazardous substance contained in all of the homogeneous materials for this part is below the limit requirement of GB/T 26572.</p> <p>X: Indicates that said hazardous substance contained in at least one of the homogeneous materials for this part is above the limit requirement of GB/T 26572.</p> <p>Lead is present due to allowed exemption in Annex III or Annex IV of the European RoHS Directive 2011/65/EU.</p> |                      |              |              |                                |                                |                                       |

## 1.0 INTRODUCTION

PCB Quartz Force Sensors are designed to measure rapidly changing compression, tensile, and impact forces for wide dynamic ranges from 10 to 100,000 lbs (44.48 N to 444.8 kN). Most sensors feature all welded construction. Voltage mode versions for low impedance output are also available.

PCB manufactures various standard sensor configurations that allow ease of installation for nearly any application. These configurations include general purpose, axial, impact, rings, 3-component, and links. In addition, custom units can be manufactured for specific requirements.

*Refer to the installation/outline drawing and specification sheet at the front of this manual for details and dimensions of the particular sensor model number(s) purchased. The following pages give a brief description of the various sensor series available, recommended mounting procedures, operation and recommended calibration.*

If you wish to learn more about sensors with built-in microelectronic circuitry, known as ICP® sensors, consult PCB's "General Guide to ICP® Instrumentation", a brochure outlining the technical specifics associated with piezoelectric force sensors. Topics covered include charge versus voltage mode systems, sensor time constants, effect of discharge time constant on low frequency response, and power requirements.


Should questions arise regarding the operation or characteristics of the Charge Mode Force Sensor products as outlined in this manual, feel free to contact an experienced applications engineer from the Force/Torque Division of PCB toll-free 888-684-0004.

## 2.0 DESCRIPTION

### IMPACT

Series 210 Impact Sensors are designed to measure compression and impact forces from 10 to 50,000 lbs (44.48 N to 222.4 kN). The flat sensing surface is located on the top of the sensor and is designed to measure force as it is applied axially to the sensor.

As highlighted in **Figure 1**, compression forces directed against the sensing surface produce a negative-going output. This force-directed input and corresponding output apply to all charge mode sensors. (If desired, adding the prefix "P" to a model number upon order can indicate polarity reversal).




Free Standing  
Impact Installation

**Figure 1 - Series 210 Charge Mode Impact Sensor**


### RINGS

Series 211B to 217B Ring Sensors are designed to measure compression forces from 10 to 100,000 lbs (44.48 N to 444.8 kN).


Each sensor is provided with a calibration sheet reflecting the sensitivity of the sensor using the supplied mounting stud. If the stud cannot be used for installation, PCB can provide a custom calibration using the desired bolt for accurate sensitivity readings. Using a different mounting stud will result in a sensitivity that differs from the original calibration. Refer to **Section 3** for recommended force ring mounting and preload requirements.



Platform  
Installation



Support




Integrated  
Link

**Figure 2 -Series 211B to 217B Force Ring Sensor**

### GENERAL PURPOSE - RADIAL

Model 218C General Purpose Sensor is designed to measure compression and impact forces from 10 to 5,000 lbs (44.48 N to 22.24 kN). Tension forces can be measured to 500 lbs. (2.224 kN). Model 084A03, a convex stainless steel cap with integral 10-32 mounting stud, is supplied for impact measurements. Polyimide film tape covers the cap surface to

reduce high-frequency ringing associated with metal-to-metal impacts.



**Figure 3 - Series 218 Charge Mode General Purpose Sensor**


#### GENERAL PURPOSE - AXIAL

Model 218A11 Axial Sensor provides performance and possesses specifications similar to the Model 218C Sensor. Model 218A11 is designed primarily to measure compression and impact from 10 to 5,000 lbs (44.48 N to 22.24 kN). Tension forces can be measured to 500 lbs (2.224 kN). The 10-32 axial electrical connector orientation associated with these sensors makes them ideal for installations where radial space is restricted or where physical connector damage may occur due to the nature of the specific application. The M7 x 0.75-6g mounting threads may be installed directly into a test structure so that the 10-32 electrical connector exits from the opposite side of the mounting fixture to prevent potential damage. This version also uses the Model 084A03 cap for impact measurements.

#### LINKS

Series 231B to 237B Charge Mode Link Sensors are designed for measuring compression and tension forces from 10 lbs. to 50,000 lbs (44.48 N to 222.4 kN), and tension forces from 10 lbs. to 30,000 lbs (44.48 N to 133.4 kN). A link consists of a


standard PCB ring sensor, preloaded between two hex end nuts. All hex nuts are internally threaded for mounting ease. External preloads are not required with these sensors, as they are internally preloaded during manufacture. Loosening or tightening of the hex nuts will change the internal preload of the sensor. At this point, the sensitivity provided on the calibration certificate will no longer represent that of the sensor. If this should occur, refer to the service and repair document for proper information.



**Figure 4 - Series 231B to 237B Charge Mode Link Sensor**


#### THREE COMPONENT RINGS

3-Component force sensors are capable of simultaneously measuring force in three orthogonal directions (X, Y, and Z). They contain three sets of quartz plates that are stacked in a preloaded arrangement. Each set responds to the vector component of applied force acting along its sensitive axis. 3-Component force sensors must be externally preloaded for optimum performance and linear operation. Versions are available with ranges up to 10,000 lbs (44.48 kN) in the Z-axis (perpendicular to the top surface), and up to 4,000 lb (18 kN) in the X and Y (shear) axes.



**Figure 5 - Charge Mode 3-Component Force Sensor**


PCB also offers 3-component force sensors with reversed X and Y (shear) axes, Models 260A31, A32, and A33 which accommodate installations with this particular need. The performance and physical characteristics of these models are the same as 260A11, A12, and A13 respectively. These models are primarily used for applications where multiple 3-component sensors need to be summed but the installation does not allow for the connectors on all sensors to be oriented in the same direction.



**Figure 6 - Series 260A11 to 260A33 Charge Mode 3-Component Force Sensor**

### 3.0 INSTALLATION

Refer to the Installation Drawing supplied with this manual for specific outline dimensions and installation details for your particular model. The specification is also included to provide details of the sensor's characteristic properties. It is important that the surface to which each sensor is mounted be perfectly flat to avoid flexing of the base, which could affect sensor sensitivity and result in erroneous data (see **Figure 7**). A good mating surface may be obtained by lapping, turning, spot facing, or surface grinding. Surface flatness should be held to within 0.001in (0.03mm) TIR over the entire mating surface. The protective cap should remain on the connector during installation to prevent contamination or damage.




**Figure 7 - Force Sensor Installation**

A light coating of silicon grease (DC-4 or equivalent) on the mating surface enhances the coupling between the mounting base and mounting surface and provides the best high-frequency response.

Connect one end of the coaxial cable to the sensor connector and the other end to the charge amplifier input connector. Make sure to tighten the cable connector to the sensor. **DO NOT** spin the sensor onto the cable, as this fatigues the cable's center pin, resulting in a shorted signal and a damaged cable.

For installation in dirty, humid, or rugged environments, it is suggested that the connection be shielded against dust or moisture with shrink tubing or other protective material. Strain relieving the cable/sensor connection can also prolong cable life. Mounting cables to a test structure with tape, clamps, or adhesives minimizes cable whip. (See **Figure 8** for

an example of a sensor installation with a securely fastened cable.)



**Figure 8 - Cable Strain Relief**

### FORCE RING INSTALLATION

The sensor is mounted using the supplied mounting stud and pilot bushing. The supplied beryllium copper stud is elastic so it allows force transmission to the sensor while holding the sensor in place. The pilot bushing centers the sensor about the mounting stud. After installing the mounting stud in the lower of the two surfaces, the pilot bushing is threaded over the mounting stud. The sensor is then placed over the stud and pilot bushing combination. The pilot bushing should fit loosely inside of the sensor inner diameter, holding it in place.

Properly machined holes for the mounting stud will ensure proper vertical orientation of the sensor. The upper surface should be installed and tightened onto the mounting stud. When installing the sensor as an integrated member, it is recommended that the supplied antifriction washers be used to eliminate the possibility of damage to the sensing surface of the sensor. This type of damage may occur when imperfections in the mounting surface grind against the sensor surface while the mounting surfaces are being twisted during installation. Refer to the installation drawing for additional mounting details.

### PRELOAD REQUIREMENTS FOR FORCE RING AND 3-COMPONENT FORCE SENSORS

PCB Force Rings (Models 211B through 217B) and 3-Component Force Sensors (Models 260A11 through 260A33) are generally installed between two parts of a test structure, as shown in **Figure 6**, with the supplied elastic beryllium-copper stud or customer-supplied bolt. During installation, the sensor should be pre-loaded to the amount specified on the specification sheet using the supplied elastic beryllium-copper stud or customer-supplied bolt. Preloading in this arrangement ensures that the sensor will perform as calibrated and have good output linearity at the sensor's lower operating range.

The stud or bolt holds the structure together and applies preload to the force ring as shown in **Figure 9**. In the typical installation, shown on the left in **Figure 9**, part of the force between the two structures is shunted through the mounting stud. The amount of force shunted may be up to 5% of the total force for the beryllium-copper stud supplied with the sensor and up to 50% for steel studs. This typical installation setup is used by PCB during standard calibrations.

Another non-typical installation is shown on the right side of **Figure 9**. In this installation, the stud or bolt used to apply the preload does not shunt part of the applied force. The plate on top of the sensor has a clearance hole that the stud or bolt passes through. In this installation, the stud or bolt is not directly connected to the top plate by its threads, as it is in the typical installation, so it does not shunt any force.

**NOTE:** *If any of the following conditions apply to the preloading of the force ring in the actual application, the sensitivity and linearity performance of the sensor will not match the standard PCB calibration values.*


**8.0** *Use of a stud or bolt other than the supplied beryllium-copper stud.*

**9.0** *Use of no stud or bolt.*

**10.0** *Use of an amount of preload other than the recommended amount.*

**11.0** *Use of the non-typical installation setup shown below.*

**12.0** *In these cases, please contact a Force/Torque Division application engineer to discuss your special calibration requirements.*



*Typical Installation*

*Non-Typical Installation*

**Figure 9 - Force Ring Sensor Installations**

PCB in-house calibration procedure requires the installation of a force ring with BeCu stud in the typical installation, in series with a NIST traceable reference sensor. Generally, a preload of 20% (full scale operating range of the force ring) is applied before recording of measurement data. Contact a PCB application specialist for proper preload requirements. Allow

the static component of the signal to discharge before calibration.

To apply pre-load, the sensor must be installed between two surfaces. A compressive force must be applied through the center axis to create the necessary pre-load. A signal that is produced by a static load should be zeroed prior to the taking a measurement. Refer to corresponding charge amplifier manual for zeroing instructions. The through-hole mounting supports platform, integrated link, and support style installations using either a through bolt or supplied stud. When installing charge mode ring and 3-component type sensors, a PCB charge amplifier should be set in long time constant mode. Likewise, a PCB signal conditioner with DC coupling capabilities is recommended if a charge mode sensor is used with an external charge converter or source follower. A DC-coupled signal conditioner will provide a longer system discharge time constant, which will result in slower signal decay. When used with a DVM or similar readout device, the installer can monitor the sensor output voltage directly for correct preloading.

3-component force sensors must be preloaded to achieve proper operation, particularly for the shear x-, and y-axis. When preloading, monitor the output from the Z-axis connector. The recommended applied preload for 3-component force sensors is 10 times their x-axis or y-axis measurement range. This preload provides the sensing crystals with the compressive loading required to achieve an output in response to shear direction input forces. When using an in-line charge converter or source follower, some models require this to be accomplished in steps, not to exceed the usable voltage. To prevent "clipping" of the signal, increments should not exceed 10 VDC.

As with force rings, the sensitivity achieved from a 3-component force sensor is dependent upon the applied preload and the elasticity characteristics of the mounting bolt or stud used. If the unit is to be installed with a stud or bolt other than the supplied elastic beryllium copper stud, a calibration using the actual mounting hardware must be preformed. Errors in sensitivity of up to 50% can result by utilizing studs or bolts of different materials.

| Force Ring Models         | Pre-Load (lbs) |
|---------------------------|----------------|
| 211B                      | 1,000          |
| 212B                      | 2,000          |
| 213B                      | 4,000          |
| 214B                      | 8,000          |
| 215B                      | 12,000         |
| 216B                      | 16,000         |
| 217B                      | 33,750         |
| <b>3-Component Models</b> |                |
| 260A11                    | 5,000          |
| 260A12                    | 10,000         |
| 260A13                    | 40,000         |

Figure 10 - Preload Requirements for Standard Models

## 4.0 OPERATION

### APPLICATION OF A FORCE

For best results, the applied force should be distributed evenly over the contact surface of the sensor. Care should be taken to limit the bending moment induced into the sensor. This is accomplished by applying a force to the sensor as close as possible to the center of the sensor. It will not be practical to limit this induced bending moment if the sensor is used singularly and if it is mounted beneath a thick plate. In this case, it may be necessary to use an arrangement of two to four sensors in a measuring platform. Independent sensor output can be monitored or the sensors can be connected electrically in parallel to measure the resulting summed forces when used in a plate type arrangement.

### TYPICAL CHARGE SYSTEM CONFIGURATION

Charge Mode Sensors require an external charge amplifier for impedance conversion. The charge amplifier should be placed as close to the sensor as possible to avoid contamination and minimize triboelectric (cable) noise. The rubbing of the strands within the cable that creates a static charge causes this triboelectric noise. It is important to keep the cable well strain relieved during testing to help reduce noise.

Each cable also has a capacitance-per-length specification, measured in Pico farads. This additional capacitance must be taken into account when determining total system capacitance. It is important to keep the low-noise cable length between the sensor and charge amplifier, or charge converter, as short as possible.

During applications in which the charge amplifier cannot be placed near the sensor, an external charge converter or source follower may be substituted. PCB Series 402 (non-signal inverting) and Series 422 (signal inverting) miniature charge amplifiers can be installed in-line with the charge sensor. These charge converters convert the sensor's high impedance charge signal to a low-impedance voltage that is transmitted

across long cables to the signal conditioner and readout. The small size of these converters allows signal conversion in remote or restricted areas.

Operation requires the connection of the force sensor first to a charge amplifier or charge converter. PCB Series 003 Low-Noise Cable should be incorporated at this location. Tighten the coaxial cable to the sensor by hand to ensure good electrical contact. **DO NOT** spin the sensor onto the mating cable connector, as this fatigues the cable's center pin, resulting in a shorted signal and a damaged cable. If operating directly to a charge amplifier, the signal may then be routed from a charge amplifier to the readout devices. If an in-line charge converter is used (Series 402 or 422), the signal may be routed from the converter to an ICP® constant-current signal conditioner, such as Series 440, 480, 482, or 484. From the signal conditioner, readout instruments may be directly connected. It is recommended to use a source follower as close as possible to the charge output sensor. Driving long cables in a charge mode system is not suggested due to the induced noise.

## 8.0 POLARITY

Compressive forces upon a charge mode force sensor produce a negative output. Tensile forces produce a positive output. Most charge amplifiers invert the signal from piezoelectric sensors. Sensors with reversed polarity are available upon request.


## 9.0 LOW-FREQUENCY MONITORING

Low frequency response of high-impedance systems is determined by the electrical characteristics of the charge amplifier. Consult the charge amplifier specifications for these characteristics.

PCB charge amplifiers have settings for short, medium, and long time constants. The short time constant is provided for use during repetitive, or transient, dynamic applications. The medium time constant is designed for slightly longer applications and some calibrations. The long time constant is provided for even longer quasi-static applications, as well as calibrations. The low frequency response of the application depends on the input resistance of the sensing system, namely the sensor cable, amplifier and readout device.


## 10.0 DISCHARGE TIME CONSTANT

The discharge time constant represents the decay rate of an input signal. One DTC represents the amount of time taken for the signal to decay to 37% of the initial peak value. As illustrated in **Figure 11**, this is an exponential decay. Approximately five DTC intervals are needed for a peak signal to naturally decay back to zero.



**Figure 11 - Characteristic Discharge Time Constant Curve**

The rule of thumb for signal discharge, as outlined in **Figure 12**, is this: for the first 10% of the DTC, the signal lost is approximately proportional to the time elapsed.



**Figure 12 - Step Function Response**

## TIME CONSTANT DETERMINATION IN CHARGE MODE SYSTEMS

Discharge Time Constant (DTC) of a charge mode system is determined by multiplying the desired operating range setting of the charge amplifier by setting of the amplifier DTC switch, located on the charge amplifier (refer to specific charge amplifier for the DTC settings). Many PCB charge amplifiers have short, medium, and long DTC settings. See the operating manual of the specific charge amplifier in question for DTC position factors.

It is possible to measure quasi-static events with piezoelectric sensors. Over the first 10% of the DTC, signal decay and accuracy represent a one-to-one relationship. Over 2% of the DTC, a 2% signal loss has occurred. Over 7%, a 7% signal loss has occurred, and so on. For 1% measurement accuracy, it is recommended that the reading be taken within the first 1% of the DTC. If it is possible to avoid AC coupling somewhere in the sensing system, try to keep the coupling time constant at least an order of magnitude longer than the DTC of the force sensor. This avoids compromising the sensor DTC.

## 8.0 CALIBRATION

A NIST (National Institute of Standards and Technology) traceable calibration graph is supplied with each force sensor certifying its charge sensitivity (pc/lb). Calibration procedures follow accepted guidelines as recommended by ANSI (American National Standards Institute), ISA (Instrument Society of America), and ISO (International Organization for Standardization). These standards provide the establishment and management of complete calibration systems, thus controlling the accuracy of a sensor's specifications by controlling measuring and test equipment accuracy. PCB is A2LA accredited for technical competence in the field of calibration, meeting the requirements of ISO/IEC 17025-1999 and ANSI/NCSL 2540-1-1994.

The charge mode force sensor, low-noise cable and 402 Source Follower may be calibrated as a system (providing mV/lb output) upon request. The sensor may be statically calibrated by using either a proving ring or standard load cells.

## 9.0 TROUBLESHOOTING

### PROBLEM: No Output

#### POSSIBLE CAUSE:

Faulty or no cable connection  
 Improper time constant (TC) switch setting  
 Low sensor capacitance  
 Faulty charge amp  
 Low sensor insulation (less than  $1 \times 10^{12}$ )

#### SOLUTION:

Properly attach or replace cable  
 Ensure switch is set properly (SHORT/ MED/ LONG)  
 Call factory for service  
 Call factory for service  
 Call factory for service

### PROBLEM: Intermittent Output

#### POSSIBLE CAUSE:

Faulty cable connection  
 Improper charge amp setting  
 Intermittent sensor

#### SOLUTION:

Properly attach or replace cable  
 Set charge amp to proper setting  
 Call factory for service

### PROBLEM: Output Drift

#### POSSIBLE CAUSE:

Faulty cable  
 Rapid Temperature Change  
 Low charge amp insulation  
 Low sensor insulation  
 Faulty sensor

#### SOLUTION:

Replace cable  
 Allow sensor to adapt to environment  
 Call factory for service  
 Call factory for service  
 Call factory for service

### PROBLEM: Improper Sensor Sensitivity

#### POSSIBLE CAUSE:

Improper XDCR sensitivity dial setting  
 Faulty sensor

#### SOLUTION:

Ensure dial is adjusted and locked into proper setting  
 Call factory for service

## 10.0 MAINTENANCE

The sensor connector must be kept clean, especially if it is operating in a dusty and/or wet environment. Because the force sensor is of welded construction, it should be returned to the factory for servicing in the event of serious malfunction.

Observe the following precautions in using the sensor:

- Do not exceed the maximum load levels for the force sensor (see specification sheet).
- Do not subject the sensor to temperatures exceeding that of the specification, normally 400°F (204°C).
- When mounting the force sensor, observe installation procedures detailed in Section 3.0 and as outlined on the specific sensor Installation Drawing to avoid overtorquing when mounting.
- Avoid metal-to-metal impacts* during applications, which can produce a high-frequency ringing. Electrical low-pass filtering or a damping material can help reduce such effects.
- Do not spin the sensor onto the cable.* This may fatigue the cable center pin, causing cable damage. Always insert the cable pin into the sensor and tighten the knurled cable nut to the sensor.

ICP® is a registered trademark of PCB Piezotronics

**MANUAL NUMBER: 18219**

**MANUAL REVISION: C**

**ECN NUMBER: 22517**

| Model Number<br>216B                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |  |  | Revision: J<br>ECN #: 50917                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |                  |                  |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------|------------------|
| <b>Performance</b><br>Sensitivity(± 15 %)<br>Measurement Range(Compression)<br>Maximum Static Force(Compression)<br>Upper Frequency Limit<br>Non-Linearity<br><b>Environmental</b><br>Temperature Range<br>Temperature Coefficient of Sensitivity<br><b>Electrical</b><br>Capacitance<br>Insulation Resistance<br>Output Polarity(Compression)<br><b>Physical</b><br>Preload<br>Stiffness<br>Size (Diameter x Height x Bolt Diameter x<br>Sensing Surface)<br>Size - ID(Hole Diameter)<br>Size - OD(Sensor)<br>Weight<br>Housing Material<br>Sealing<br>Electrical Connector<br>Electrical Connection Position |  |  | <b>OPTIONAL VERSIONS</b><br>Optional versions have identical specifications and accessories as listed for the standard model except where noted below. More than one option may be used.<br><br><b>M</b> - Metric Mount<br>Supplied Accessory: Model 080A82 Assembly Lubricant<br>Supplied Accessory: Model 082B06 Anti-Friction Washer<br>Supplied Accessory: Model M081A16 Mounting Stud, M22 x 2.00 x 1.900, BeCu<br>Supplied Accessory: Model M083B06 Pilot Bushing<br><br><b>P</b> - Positive Output Polarity<br>Output Polarity(Compression)<br><br><b>W</b> - Water Resistant Cable<br>Electrical Connector<br>Electrical Connection Position |                  |                  |
| <b>ENGLISH</b><br>18 pC/lb<br>≤ 80,000 lb<br>90,000 lb<br>40 kHz<br>≤ 1.25 % FS<br>-100 to +400 °F<br>≤ 0.03 %/°F<br>80 pF<br>≥ 1E12<br>Negative<br>16,000 lb<br>74 lb/μin<br>2.05 in x 0.590 in x 1 in x 1.750<br>in<br>1.025 in<br>2.05 in<br>5.48 oz<br>Stainless Steel<br>Hermetic<br>10-32 Coaxial Jack<br>Side                                                                                                                                                                                                                                                                                           |  |  | Positive<br>Positive<br>Molded Integral Cable<br>Side<br>Molded Integral Cable<br>Side                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |                  |                  |
| <b>SI</b><br>4,047 pC/kN<br>≤ 355.86 kN<br>400.32 kN<br>40 kHz<br>≤ 1.25 % FS<br>-73 to +204 °C<br>≤ 0.054 %/°C<br>80 pF<br>≥ 1E12<br>Negative<br>71.172 kN<br>13 kN/μm<br>52.9 mm x 15 mm x 26 mm x<br>44.5 mm<br>26.04 mm<br>52 mm<br>155 gm<br>Stainless Steel<br>Hermetic<br>10-32 Coaxial Jack<br>Side                                                                                                                                                                                                                                                                                                    |  |  |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |                  |                  |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |  |  | <b>NOTES:</b><br>[1]Estimated using rigid body dynamics calculations.<br>[2]Low frequency response and system noise dependent on choice of external signal conditioning electronics.<br>[3]Zero-based, least-squares, straight line method.<br>[4]Typical.                                                                                                                                                                                                                                                                                                                                                                                           |                  |                  |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |  |  | <b>SUPPLIED ACCESSORIES:</b><br>Model 080A82 Assembly Lubricant<br>Model 081A16 Mounting Stud, 7/8-14 x 1.900, BeCu<br>Model 082B06 Anti-Friction Washer<br>Model 083B06 Pilot bushing (for Models 206C and 216B)                                                                                                                                                                                                                                                                                                                                                                                                                                    |                  |                  |
| Entered: LK                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |  |  | Engineer: MJK                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        | Sales: KWW       | Approved: RPF    |
| Date: 07/13/2020                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |  |  | Date: 07/13/2020                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     | Date: 07/13/2020 | Date: 07/13/2020 |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |  |  | Spec Number:<br>216-2010-80                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |                  |                  |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |  |  | Phone: 716-684-0001<br>Fax: 716-684-0987<br>E-Mail: info@pcb.com                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |                  |                  |
| All specifications are at room temperature unless otherwise specified.<br>In the interest of constant product improvement, we reserve the right to change specifications without notice.<br>ICP® is a registered trademark of PCB Piezotronics, Inc.                                                                                                                                                                                                                                                                                                                                                           |  |  | 3425 Walden Avenue, Depew, NY 14043                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |                  |                  |


6689

PCB Piezotronics Inc. claims proprietary rights in the information disclosed hereon. Neither it nor any reproduction thereof will be disclosed to others without written consent of PCB Piezotronics Inc.


| APPLICATION |         |     |
|-------------|---------|-----|
| NEXT ASS'Y  | USED ON | VAR |
|             |         |     |

| REVISIONS |             |     |      |       |
|-----------|-------------|-----|------|-------|
| REV       | DESCRIPTION | ECN | DATE | APP'D |
|           |             |     |      |       |

Ø1.025(Ø26.04)  
THRU HOLE



MODEL 082B06  
ANTI-FRICTION  
WASHER  
(SUPPLIED)



- △ THESE SURFACES TO BE FLAT AND PARALLEL TO WITHIN .001(0.03) TIR.  
1.) SEE SHEET TWO FOR MOUNTING INSTRUCTIONS.

## UNLESS SPECIFIED TOLERANCES

| DIMENSIONS IN INCHES             | DIMENSIONS IN MILLIMETERS<br>(IN PARENTHESIS) |
|----------------------------------|-----------------------------------------------|
| DECIMALS XX ±.01                 | DECIMALS XX ±0.3                              |
| XXX ±.005                        | XXX ±0.13                                     |
| ANGLES ±2 DEGREES                | ANGLES ±2 DEGREES                             |
| FILLETS AND RADII<br>.003 - .005 | FILLETS AND RADII<br>(0.07 - 0.13)            |

|                                                            |     |         |      |     |         |
|------------------------------------------------------------|-----|---------|------|-----|---------|
| DRAWN                                                      | TW  | 7/16/97 | MFG  | STA | 7/16/97 |
| CHK'D                                                      | DM  | 7/16/97 | ENGR | ZAB | 7/16/97 |
| APP'D                                                      | WSE | 7/16/97 |      |     |         |
| TITLE<br>INSTALLATION DRAWING<br>MODEL M216B<br>FORCE RING |     |         |      |     |         |

**PCB** PIEZOTRONICS, INC.  
3425 WALDEN AVE. DEPEW, NEW YORK 14043  
PHONE: (716) 684-0001

|                             |                  |
|-----------------------------|------------------|
| CODE<br>IDENT. NO.<br>52681 | DWG. NO.<br>6689 |
| SCALE: FULL                 |                  |
| SHEET 1 OF 2                |                  |

6689

PCB Piezotronics Inc. claims proprietary rights in the information disclosed hereon. Neither it nor any reproduction thereof will be disclosed to others without written consent of PCB Piezotronics Inc.

## APPLICATION

|            |         |     |
|------------|---------|-----|
| NEXT ASS'Y | USED ON | VAR |
|            |         |     |

## REVISIONS


| REV | DESCRIPTION     | ECN | DATE | APP'D |
|-----|-----------------|-----|------|-------|
|     | -SEE SHEET ONE- |     |      |       |

MODEL M081A16  
STUD  
M22 X 2.00-6g  
TYP EACH END  
(SUPPLIED)

MODEL M083B06  
PILOT BUSHING  
(SUPPLIED)

ANTI-FRICTION  
WASHER


1.900  
(48.26)



TYP STUD MOUNTING  
INSTALLATION

MOUNTING HOLE PREPARATION:

DRILL  $\phi .787(\phi .20.00)$   $\triangle 2$   
X 1.00(25.4)  $\nabla$   
TAP M22 X 2.00-6H  
X .750(19.05)  $\nabla$   
PERFECT THREAD



3.) SEE MANUAL FOR PRELOAD INSTRUCTIONS.

$\triangle 2$  DRILL PERPENDICULAR TO MOUNTING SURFACE TO WITHIN  $\pm .001^{\circ}$ .

$\triangle 1$  MOUNTING SURFACE UNDER FORCE RING MUST BE FLAT WITHIN  
.001(0.03) TIR WITH A 63/ (1.6/) FINISH.

## UNLESS SPECIFIED TOLERANCES

| DIMENSIONS IN INCHES             | DIMENSIONS IN MILLIMETERS<br>(IN PARENTHESIS) |
|----------------------------------|-----------------------------------------------|
| DECIMALS XX $\pm .01$            | DECIMALS XX $\pm 0.3$                         |
| XXX $\pm .005$                   | XXX $\pm 0.13$                                |
| ANGLES $\pm 2$ DEGREES           | ANGLES $\pm 2$ DEGREES                        |
| FILLETS AND RADII<br>.003 - .005 | FILLETS AND RADII<br>(0.07 - 0.13)            |
| DD011 REV. A 05/26/95            |                                               |

|       |                                                   |         |      |            |         |
|-------|---------------------------------------------------|---------|------|------------|---------|
| DRAWN | <i>rw</i>                                         | 7/16/97 | MFG  | <i>RJA</i> | 7/16/97 |
| CHK'D | <i>dm</i>                                         | 7/16/97 | ENGR | <i>LJB</i> | 7/16/97 |
| APP'D | <i>WST</i>                                        | 7/16/97 |      |            |         |
| TITLE | INSTALLATION DRAWING<br>MODEL M216B<br>FORCE RING |         |      |            |         |

**PCB** PIEZOTRONICS, INC.  
3425 WALDEN AVE. DEPEW, NEW YORK 14043  
PHONE: (716) 684-0001

|                             |                      |
|-----------------------------|----------------------|
| CODE<br>IDENT. NO.<br>52681 | OWG. NO.<br><br>6689 |
| SCALE: FULL                 | SHEET 2 OF 2         |